


Quick Start Guide – 7SDI-1000 SDI-12 Adapter

Procedures for connecting and configuring Greenspan SDI12 Adapter Unit.
Further details in the sensor manual included on the Greenspan CD.


You should have received:

- CD Manuals & Software
- Greenspan SDI-1000 SDI-12 Adapter
- Bare Wire to SDI-1000 Adapter Cable (if required)

SDI-12 Adapter with 3000 series Logging sensor



Or if using an analogue output PS7000 or PS1000 Sensor



SDI-12 Adapter Quick Start Guide